

Dominion Virginia Electric Power (DOM)

1. **Ladysmith #2 500/230 kV Transformer Sectionalized** – Restores the 500 kV Bus Breakers for a fault on the Ladysmith #2 500/230 kV transformer.
 - Effective November 23rd, 2021