# Transmission Expansion Advisory Committee – JCPL Supplemental Projects

October 3, 2023

## Needs

Stakeholders must submit any comments within 10 days of this meeting in order to provide time necessary to consider these comments prior to the next phase of the M-3 process



### JCPL Transmission Zone M-3 Process Morris Park Substation

Need Number: JCPL-2023-011

**Process Stage:** Need Meeting 10/3/2023

**Project Driver:** 

System Performance and Operational Flexibility

**Specific Assumption Reference:** 

**Global Factors** 


System reliability and performance

Add/Expand Bus Configuration

Load at risk and/or customer affected

#### **Problem Statement:**

- The existing 230 kV and 115 kV sources to Morris Park Substation are fed radially. Gilbert – Martins Creek 230 kV and Gilbert – Pequest River 115 kV Lines are configured as three terminal lines.
- Morris Park serves approximately 13 MW of load and 4,240 customers which will be outaged by an N-1-1 contingency of the Gilbert – Martins Creek 230 kV and Gilbert – Pequest River 115 kV Lines.
- The existing 115 34.5 kV transformer at Morris Park was manufactured in 1953 and is approaching end of life.





JCPL Transmission Zone M-3 Process
Kittatinny-Yards Creek 230 kV Misoperation Relays

Need Number: JCPL-2023-035

Process Stage: Need Meeting 10/3/2023

**Project Driver:** 

Equipment Material Condition, Performance and Risk

#### **Specific Assumption References:**

**Global Factors** 

- System reliability and performance
- Substation / line equipment limits


#### **Upgrade Relay Schemes**

- Relay schemes that have a history of misoperation
- Obsolete and difficult to repair communication equipment (DTT, Blocking, etc.)
- Communication technology upgrades
- Bus protection schemes

#### **Problem Statement:**

- FirstEnergy has identified protection schemes using a certain vintage of relays and communication equipment that have a history of misoperation.
- Proper operation of the protection scheme requires all the separate components perform adequately during a fault
- In many cases the protection equipment cannot be repaired due to a lack of replacement parts and available expertise in the outdated technology.
- Transmission line ratings are limited by terminal equipment.

#### Continued on next slide...





## JCPL Transmission Zone M-3 Process Kittatinny-Yards Creek 230 kV Misoperation Relays

...Continued from previous page

Need Number	Transmission Line / Substation Locations	Existing Line Rating (SN / SE)	Existing Conductor Rating (SN / SE)
JCPL-2023-035	Kittatinny-Yards Creek 230 kV M1027 Line	648 / 648	709 / 869

## Questions?



# Appendix

## High level M-3 Meeting Schedule

Assumptions	Activity	Timing		
, 1000	Posting of TO Assumptions Meeting information	20 days before Assumptions Meeting		
	Stakeholder comments	10 days after Assumptions Meeting		
Needs	Activity	Timing		
	TOs and Stakeholders Post Needs Meeting slides	10 days before Needs Meeting		
	Stakeholder comments	10 days after Needs Meeting		
Solutions	Activity	Timing		
	TOs and Stakeholders Post Solutions Meeting slides	10 days before Solutions Meeting		
	Stakeholder comments	10 days after Solutions Meeting		
		l		
Submission of	Activity	Timing		
Supplemental	Do No Harm (DNH) analysis for selected solution	Prior to posting selected solution		
Projects & Local	Post selected solution(s)	Following completion of DNH analysis		
Plan	Stakeholder comments	10 days prior to Local Plan Submission for integration into RTEP		
	Local Plan submitted to PJM for integration into RTEP	Following review and consideration of comments received after		

posting of selected solutions

## **Revision History**

9/22/2023 - V1 – Original version posted to pjm.com

PJM TEAC- JCPL Supplemental 10/03/2023